



anchor industries



May, 2012


Replace GM Torque Strut Mounts and Brackets Together Address the Cause, not just the Symptom

Many of today's late model General Motors vehicles have transverse mounted engine designs that require torque strut mounts and torque strut brackets to help dampen engine torque, vibration and noise (refer to image on the right).

The bushings and rubber compound within the torque strut mounts and brackets can wear out over time, due to constant driveline torque and extreme engine heat. When one component wears out, it will put added stress on the connected part, which may cause the corresponding part to fail as well.

The solution is to always replace both the torque strut mounts and brackets together to ensure the repair is done right by fixing the root cause, not just the symptom.

The GM torque strut mounts and corresponding torque strut brackets listed below should always be replaced at the same time.



Torque Strut Brackets

GM Torque Struts	Corresponding Torque Strut Brackets
2866 GM: Allure, Impala, Cutlass, Grand Prix, Intrigue, LaCrosse, 2.2L, 3.1L, 3.5L, 3.4L, 3.6L, 3.8L, 1994-2009	2901 GM: Century, Grand Prix, Impala, Regal, 3.1L 3.4L, 3.8L, 1994-2005 3088 GM: Impala, Monte Carlo, Grand Prix, Intrigue, LaCrosse/Allure, Regal, 3.5L, 3.6L, 3.8L, 1996-2009 3104 GM: Impala, Monte Carlo Allure, LaCrosse/Allure, 3.5L, 3.9L, 5.3L, 2006-2009
2899 GM: Aztek, Montana, Rendezvous, Terraza, Transport, 3.4L, 3.5L, 3.6L 3.9L, 1996-2008	2900 GM: Aztek, Montana, Rendezvous, Terraza, Transport, 3.4L, 3.5L, 3.6L 3.9L, 1997-2007 3088 GM: Impala, Monte Carlo, Grand Prix, Intrigue, LaCrosse/Allure, Regal, 3.5L, 3.6L, 3.8L, 1996-2008
3090 GM: Terraza, Monte Carlo, Impala, Grand Prix, 3.5L, 3.9L, 5.3L, 1996-2011	2900 GM: Aztek, Montana, Rendezvous, Terraza, Transport, 3.4L, 3.5L, 3.6L 3.9L, 1997-2007 3088 GM: Impala, Monte Carlo, Grand Prix, Intrigue, LaCrosse/Allure, Regal, 3.5L, 3.6L, 3.8L, 1996-2009 3104 GM: Impala, Monte Carlo Allure, LaCrosse/Allure, 3.5L, 3.9L, 5.3L, 2006-2011
3133 GM: Acadia, Enclave, Outlook, 3.6L 2007-2008	3143 GM: Acadia, Enclave, Outlook, 3.6L 2007-2008



Bushings and rubber compound can wear out over time due to constant engine torque and extreme temperature variances.



Torque Strut Mount

For more information, please contact our
Technical Support Department at 800-444-4616

The Most Trusted Name In Engine & Transmission Mounts Since 1933!

